

REPORT of SURVEY for REPAIRS.

Change 3/4 Juncos 10,592
No. 10692 Survey held at Liverpool Date Dec 11/3/57 18 57
 on the Iron 75th Eclipse Master M^r Barker
 Tonnage 329 Built at Hull When built 1849
 By whom built _____ Owners Beard
 Port belonging to Hull Destined Voyage Stettin
 If Surveyed Afloat or in Dry Dock on the ground

Last Survey, No. 247 Port Iron Classed A 1

REPAIRS See Vessel not Registered No. 5

Present Condition of the

Decks	} <u>Good</u>	Ironails	} <u>Good</u>	Windlass and Capstan
Waterways		Breasthooks and Stenson		Pumps
Comings		Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.
Lower Deck Beams & Fastenings		Keelsons		Sails
Planksheers		Clamps and Shelves		Anchors
Sheerstrakes		Ceiling		Cables
Topsides		Rudder		Hawsers and Warps
Wales		Standing & Running Rigging		
Plank (Bottom) and Counter				

General Observations and Opinion,

*Appears in a condition for the safe conveyance of dry
 & perishable cargoes to & from all parts of the world & recommends her to
 continue as Clapped*

The Amount of Fee.....£ 2 : - - is received by me,

Special..... - : - : -

Certificate (if required) - : 10 : -

Committee's Minute

Character assigned



© 2019

Lloyd's Register

Iron 430A-0229

"Eclipse" 10692.



© 2019

Lloyd's Register
Foundation