

No. 2

Survey held at

Liverpool D.C.A.

Date

July 27

1855

on the

Iron Ship Talavera

Master

R. Blair

Tonnage

1160

Built at

Liverpool

When built

1854

By whom built

Cato Miller & Co

Owners

Miller & Co

Port belonging to

Liverpool

Destined Voyage

If Surveyed Afloat or in Dry Dock

Dry Dock

Last Survey, No.

Port of

Classed

A.1

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan 3

H

Pumps

2 1/2 Mals

Boats

3

Masts, Yards, &c.

Sails

Anchors

No. of 3

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Appears in good repair & fit for the safe conveyance
of Dry & Perishable cargoes & in my opinion should
remain as classed

Committee's Minute

28th

August

1855

Character assigned

21st

September