

## ANNUAL SURVEYS.

1100

No. 2598 Survey held at Leith Date 19<sup>th</sup> June 1856  
 on the Iron Clipper Schooner Prince of Wales Master James Johnston  
 Tonnage 148 Built at Aberdeen When built 1845  
 By whom built William Simpson & Co Owners London & Leith Old Shipping Co  
 Port belonging to Leith Destined Voyage London  
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 821Port of LeithClassed 12A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>In best order</u>	Windlass and Capstan <u>Quill Wind Strong</u>
Waterways <u>Q</u>	Breasthooks and Stemson <u>In best order</u>	Pumps <u>2 Metal Good</u>
Comings <u>Q</u>	Transoms, Pointers, and Crutches <u>In best order</u>	Boats <u>2 Q</u>
Upper Deck Beams & Fastenings <u>Strong</u>	Timbers of the Frame <u>In best order</u>	Masts, Yards, &c. <u>Q</u>
Lower Deck Beams & Fastenings <u>Q</u>	Keelsons <u>In best order</u>	Sails <u>Q</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>In best order</u>	Anchors No. of <u>20 Bower, 1 Stream, 1 Kedge</u>
Sheerstrakes <u>In best order</u>	Ceiling <u>In best order</u>	Cables <u>Complete</u>
Topsides <u>In best order</u>	Rudder <u>Strong</u>	Hawsers and Warps <u>Good</u>
Wales <u>In best order</u>	Copper <u>When put on</u>	Standing & Running Rigging <u>Q</u>
Plank (Bottom) and Counter <u>In best order</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	

General Observations and Opinion,

This vessel is at present in a good state of repair throughout, and is well found in stores. I am of opinion that she may remain as classed 12A1. She has been Docked at present merely to get Bottom cleaned.

Committee's Minute

1<sup>st</sup> July 1856

Character assigned

12A1

Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_

Port of \_\_\_\_\_

Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Caulking of Bottom, Deck, & Waterways _____	

General Observations and Opinion,

Committee's Minute

1<sup>st</sup> July 1856

Character assigned