

ANNUAL SURVEYS.

No. 1039 Survey held at Aberdeen Date Feb 12th 1859
 on the Edinburgh Screw Steam Master John Murray
 Tonnage 94 Built at Glasgow When built 1857
 By whom built Smith & Rogers Owners Edw^d James Filder
 Port belonging to London Destined Voyage Cadiz
 If Surveyed Afloat or in Dry Dock On port at Ship

Last Survey, No. 1483 Port of Iron Classed G.A.S.

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>cl^d</u>	Breasthooks and Stemson <u>none</u>	Pumps <u>4</u> <u>Good</u>
Comings <u>cl^d</u>	Transoms, Pointers, and Crutches <u>—</u>	Boats <u>3</u> <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good where seen</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>none</u>	Keelsons <u>Good</u>	Sails <u>one suit</u> <u>Good</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>cl^d</u>	Anchors No. of <u>4</u> <u>Good</u>
Sheerstrakes <u>cl^d</u>	Ceiling <u>cl^d</u>	Cables <u>110 fathoms</u> <u>cl^d</u>
Topsides <u>cl^d</u>	Rudder <u>cl^d</u>	Hawsers and Warps <u>Good</u>
Wales <u>cl^d</u>	Copper <u>none</u> When put on <u>—</u>	Standing & Running Rigging <u>cl^d</u>
Plank (Bottom) and Counter <u>cl^d</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Repairs at present time. On acct of damage received by striking the bar coming into Aberdeen harbour, several of the plates in plating bottom much damaged, which has been removed & renewed with plates of size thicker, all necessary repairs has been complete with, she is in a good & efficient state in my opinion Eligible to remain as classed.

Committee's Minute 18th February 1859 State & in my opinion Eligible to remain as classed.
 Character assigned 97 1 record damage Will M. Wallis
12/6 Fee for Change of Owner & Certificate (if required) Paid

No. _____ Survey held at _____ Date _____ 185____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18

Character assigned _____