

1935  
ANNUAL SURVEYS.

22501

No. 649 on the Iron Ship "Conflict" Survey held at London Date June 14<sup>th</sup> 1859 Master J. R. Ows  
Tonnage 1305 Built at Liverpool When built 1855  
By whom built J. R. Ows Owners Smith  
Port belonging to Liverpool Destined Voyage  
If Surveyed Afloat or in Dry Dock Carter's dry dock.

Last Survey, No. 1617 Port of Iron Classed A. 1.

The present Condition of the

Decks	Caulked	Treenails		Windlass and Capstan	good
Waterways	"	Breasthooks and Stemson		Pumps	"
Comings	good	Transoms, Pointers, and Crutches		Boats	good and sufficient
Upper Deck Beams & Fastenings	Iron	Timbers of the Frame	Iron	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers	good condition	Clamps and Shelves	good	Anchors No. of	"
Sheerstrakes	where seen	Ceiling	condition	Cables	"
Topsides		Rudder	where seen	Hawsers and Warps	"
Wales		Copper	When put on	Standing & Running Rigging	"
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Now done, - Bottom scraped and coated with two coats of paint and one of tallow, - She now appears in good condition and in my opinion eligible to remain as classed.

Committee's Minute 26<sup>th</sup> June 1859

Character assigned

Certificate (if required)

No. 272 on the Iron Ship "Glenroy" Survey held at London Date May 19<sup>th</sup> 1859 Master L. A. M. Alpine  
Tonnage 1220 Built at Camberton When built 1854  
By whom built C. M. Alpine Owners C. M. Alpine  
Port belonging to Glasgow Destined Voyage  
If Surveyed Afloat or in Dry Dock Lampley's upper dry dock and E. J. dock.

Last Survey, No. 1635 Port of Iron Classed G. A. 1.

The present Condition of the

Decks	Caulked	Treenails		Windlass and Capstan	good
Waterways	"	Breasthooks and Stemson		Pumps	"
Comings	good	Transoms, Pointers, and Crutches		Boats	good and sufficient
Upper Deck Beams & Fastenings	Iron	Timbers of the Frame	Iron	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	Iron	Keelsons	"	Sails	"
Planksheers	good	Clamps and Shelves	good	Anchors No. of	"
Sheerstrakes	condition	Ceiling	condition	Cables	"
Topsides	where seen	Rudder	where seen	Hawsers and Warps	"
Wales		Copper	When put on	Standing & Running Rigging	"
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Now done, Ceiling in the flat at bottom of fore and aft removed and upward of 1000 Rivets in the lower edges of plating renewed, plating scraped clean and Portland Cement laid on, extending from middle line to turn of bilge, bottom scraped externally and coated with paint and grease, Deck Caulked, - She now appears in good condition, and in my opinion eligible to remain as classed.

Committee's Minute 26<sup>th</sup> June 1859

Character assigned

Certificate (if required)

Charge for attendance £ 2-2 no repair fee - 20/7/59