

ANNUAL SURVEYS.

1944
 No. 13875 Survey held at Liverpool Date July 13th 1859
 on the Iron Ship Splavera Master R. Blair
 Tonnage 1140 Built at Liverpool When built 1854
 By whom built Cato & Co Owners Miller & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 1179 Port of Iron Classed A 1
58

The present Condition of the

| | | |
|-------------------------------|----------------------------------|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Keelsons | Sails |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper | Standing & Running Rigging |
| Plank (Bottom) and Counter | When put on | |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

The Ship has been Scraped clean the plating and rivets good.
 Is now in a fit and efficient state for the safe conveyance
 of Dry and perishable Cargoes to and from all parts of the
 Committee's Minute 22nd July 1859 word and in my opinion should
 Character assigned A 1 retain her present Character Merits

Certificate (if required)

"Talavera"

"Mars" 15845



© 2019

Lloyd's Register
Foundation