

ANNUAL SURVEYS.

Iron Ships

No. *902*

on the *S.S. Asia*

Tonnage *923*

By whom built

Port belonging to *London*

If Surveyed Afloat or in Dry Dock

Survey held at

Asia

Built at

Sunderland

When built

1858

Date

March 22nd

18*60*

Master

S. Xenos

Owners

S. Xenos

When built

1858

Destined Voyage

Lungley's lower dock

Last Survey, No. *1588*

Port of *Iron*

Classed *A 1*

58.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

~~Strenuous~~ Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good where seen

The bottom coated with Red lead - This vessel appears in good condition and is eligible in my opinion to remain clasped A 1

Committee's Minute

Character assigned

11th May 1860

A 1

Thos. W. Mason

Certificate (if required)

No. *688*

on the *S. "Conflict" of Iron*

Tonnage *1326*

By whom built

Port belonging to *Liverpool*

If Surveyed Afloat or in Dry Dock

Survey held at

London

Built at

Liverpool

When built

1855

Destined Voyage

Millwall dry dock

Date

April 30th

18*60*

Master

R. Deas

Owners

Smith jun^r

Last Survey, No. *1935*

Port of *Iron*

Classed *A 1*

6.59

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

~~Strenuous~~ Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

The bottom coated outside - This vessel is now in good condition and is eligible in my opinion to remain clasped A 1

Committee's Minute

Character assigned

11th May 1860

A 1

Thos. W. Mason

Certificate (if required)