

2183

ANNUAL SURVEYS.

Rec. 8/6/60

No. 1690 Survey held at Glasgow Date 6th June 1860
 on the San Diego Mosquito Master W. S. Phipps
 Tonnage 198 Built at Newfrew When built 1859
 By whom built Camp Henderson & Son Owners Mason & Co.
 Port belonging to London Destined Voyage Cuba
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 1807 Port of Lyon Classed g.s.t.
1,59

The present Condition of the

| | | | | | |
|-------------------------------|-----------------|----------------------------------|-------------------------------------|----------------------------|----------------------------|
| Decks | <u>Good</u> | Rivet Fastenings | <u>Good</u> | Windlass and Capstan | <u>Good</u> |
| Waterways | <u>do</u> | Breasthooks and Stenson | <u>do</u> | Pumps | <u>do</u> |
| Comings | <u>do</u> | Transoms, Pointers, and Crutches | <u>do</u> | Boats | <u>do</u> |
| Upper Deck Beams & Fastenings | <u>do</u> | Timbers of the Frame | <u>do</u> | Masts, Yards, &c. | <u>Complete & Good</u> |
| Lower Deck Beams & Fastenings | <u>do</u> | Keelsons | <u>do</u> | Sails | <u>do</u> |
| Planksheers | <u>do</u> | Clamps and Shelves | <u>do</u> | Anchors No. of | <u>do</u> |
| Sheerstrakes | <u>Rotating</u> | Ceiling | <u>do</u> | Cables | <u>do</u> |
| Topsides | <u>do</u> | Rudder | <u>do</u> | Hawsers and Warps | <u>do</u> |
| Wales | <u>do</u> | Copper | <input checked="" type="checkbox"/> | Standing & Running Rigging | <u>do</u> |
| Plank (Bottom) and Counter | <u>do</u> | When put on | <input checked="" type="checkbox"/> | | |

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Part New & Good
 Bottom Re-coated with Red Lead, Sheels of Stanchions and Deck re-caulked
 is now in a good and efficient condition and may continue as before

Committee's Minute 19th June 1860.
 Character assigned G.A.

© 2019
 Lloyd's Register
 Foundation

Certificate (if required)

IRON 434 - 0280