

REPORT of SURVEY for REPAIRS.

Rec 13/12/60

No. 16682 Survey held at Liverpool Date 23 Oct 22 Nov 1860
 on the Iron Ship Hippolyta Master Hounsell
 Tonnage 853 Built at Port Glasgow When built 1856
 By whom built _____ Owners Heap & Son
 Port belonging to Liverpool Destined Voyage Pangoon
 If Surveyed Afloat or in Dry Dock Dry Dock and Afloat

Last Survey, No. 1998 Port Iron Classed 12 A1
 39

REPAIRS

Has now had the whole of the ceiling lifted and in consequence of corrosion had three garboard stake plates and two others in the bottom replaced with new, the whole of rivets in the bottom carefully examined and all which were defective have been renewed.

The inside of bottom coated with Portland Cement, Ceiling relaid and ship painted

Present Condition of the

Decks	Freemasts	Windlass and Capstan	<u>good</u>
Waterways	Breasthooks and Stemson	Pumps	"
Comings	Transoms, Pointers, and Crutches	Boats	"
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	Keelsons	Sails	<u>well found</u> "
Planksheers	Clamps and Shelves	Anchors	No. of <u>3 No 1 St 2 Kedges</u>
Sheerstrakes	Ceiling	Cables	"
Topsides	Rudder	Hawsers and Warps	<u>sufficient</u>
Wales	Gopper <u>Paint</u> When put on <u>present time</u>	Standing & Running Rigging	<u>and good</u>
Plank (Bottom) and Counter			

General Observations and Opinion,Caulking of Bottom, Deck, & Waterways. appears good

Is in a fit state for the safe conveyance of dry and perishable Cargoes to and from all parts of the World and eligible to retain her present Class

J MinshurstThe Amount of Fee.....£ 2 : " : " is received by me,Special..... 2 : 2 : 0 10/12/60Ded. 40% Certificate (if required) " : " : "Committee's Minute 14th December 1860Character assigned 12 A1

© 2019

Lloyd's Register
Foundation

IRON434-0413

"Hippolyta" 16682



© 2019

Lloyd's Register
Foundation