

ANNUAL SURVEYS.

No. 454 Survey held at London Date 5th to 8th June 1861
 on the Iron Screw "Hutton Chaytor" Master _____
 Tonnage 529 Built at Newcastle When built 1855
 By whom built 424 Owners Gen & Screw Co
 Port belonging to London Destined Voyage Cardiff & Lisbon
 If Surveyed Afloat or in Dry Dock Upper Globe dry dock

Last Survey, No. 1525 Port of Iron Ships. Classed 6A1
57

The present Condition of the

Decks	} <u>Good</u>	Treenails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan <u>without Steam winch</u>	
Waterways		Breasthooks and Stemson		Pumps <u>3 No</u>	<u>Good</u>
Comings		Transoms, Pointers, and Crutches		Boats <u>3 No</u>	<u>do</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	<u>do</u>
Planksheers		Clamps and Shelves		Anchors No. of <u>3 B. 1 S & 1 K</u>	
Sheerstrakes		Ceiling		Cables	<u>proof</u>
Topsides		Rudder		Hawsers and Warps <u>4 No</u>	<u>do</u>
Wales	<u>Seen</u>	Copper	When put on	Standing & Running Rigging	<u>do</u>
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

Bottom cleaned and coated. 2 planks of ceiling of flat lifted and the asphalt coating where seen good. one angle iron No. 6 beam renewed and one strengthened by an angle iron on lower edge. Waterways recaulked. She appears where seen in good condition and in my opinion may continue as above at

Committee's Minute 21st June 1861

Will C. Davey

Character assigned 6A1

Certificate (if required)

No. _____ Survey held at _____ Date _____ 185____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	When put on
Plank (Bottom) and Counter		Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18

Character assigned _____



© 2019

Certificate (if required).

IRON435-0075

28 ^e/10
16 3
44.5

5788
14-

8/16

