

2523

ANNUAL SURVEYS.

No. 104 Survey held at London Date 31st Sept to 2nd Sept 1861
 on the Iron Ship "Samson" Master Thompson
 Tonnage 590 Built at Sunderland When built 1860
 By whom built _____ Owners E. Gouley
 Port belonging to Sunderland Destined Voyage for Natal
 If Surveyed Afloat or in Dry Dock Commercial dry dock

Last Survey, No. 2134 Port of Iron Classed GA
 60

The present Condition of the

Decks	<u>Good</u>	Greenails	<u>Good where seen</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	<u>used</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>where</u>	Keelsons		Sails	<u>sufficient</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	<u>where</u>
Topsides		Rudder		Hawsers and Warps	
Wales	<u>seen</u>	Copper	<u>When put on</u>	Standing & Running Rigging	<u>seen</u>
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

Bottom coated, and a hole in the port bow joined and lined, and six frames strengthened. She is now in good and efficient condition eligible to remain as classed

Committee's Minute 13th September 1861

Character assigned GA

Certificate (if required)

No. 134 Survey held at London Date 2nd Sept 1861
 on the Iron Ship "White Eagle" Master Williams
 Tonnage 993 Built at Glasgow When built 1853
 By whom built _____ Owners Robinson
 Port belonging to London Destined Voyage for
 If Surveyed Afloat or in Dry Dock Porters dry dock

Last Survey, No. 2293 Port of Iron Ships Classed GA
 10. 60

The present Condition of the

Decks	<u>Good</u>	Greenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	<u>used</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>where</u>	Keelsons	<u>where</u>	Sails	<u>sufficient</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	<u>where</u>
Topsides		Rudder	<u>seen</u>	Hawsers and Warps	
Wales	<u>seen</u>	Copper	<u>When put on</u>	Standing & Running Rigging	<u>seen</u>
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

This ship is in good and efficient condition eligible to remain as classed

Committee's Minute 13th September 1861

Character assigned GA

Certificate (if required).

IRON435-0141