

No. 783 Survey held at Liverpool Date Nov 19th Dec: 3 1867
 on the B^h Bontek (Hon) Master R B Jeffreys
 Tonnage 245 Built at Liverpool When built 1855
 By whom built — Owners Doming B.
 Port belonging to Lpool Destined Voyage Guatemala
 If Surveyed Afloat or in Dry Dock in 92 & at Leab

Last Survey, No. 2339 Port of Iron Classed A1
2.61

The present Condition of the

Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timber of the Frame
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Bottom
 When put on at present

Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Sails
 Anchors No. of 3 Brou 1 Dm. 1 Kedge
 Cables
 Hawseers and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways All satisfactory when turned

Appears in a condition for the safe conveyance of dry & perishable cargoes
 to & from all parts of the world & recommends her to continue as classed the Owners
 are aware of the survey required by the rules as the period of 6 years will expire
 Committee's Minute 13th December 1867 at the end of the present year

Character assigned

Certificate (if required).

IRON435-0238