

2721

ANNUAL SURVEYS.

27558

Recd. 13/3/62

No. 109 on the Iron S. Knight Errant Master Quine Date 24th Feb^y to 1st Mar 1862
 Survey held at Londou
 Tonnage 1312 Built at Hull When built 1858
 By whom built _____ Owners Blescher &
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Portoon Victoria dock

Last Survey, No. 2112 Port of Iron Classed 12 A 1
60

The present Condition of the

| | | | |
|---|--|---|---|
| Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ | Treenails <u>Rivets</u> Breasthooks and Stenson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder <u>part rivetted</u> Copper _____ When put on _____ | Windlass and Capstan _____ Pumps <u>4 No</u> Boats <u>4 No</u> Masts, Yards, &c. _____ Sails _____ Anchors No. of <u>3 B. 15 + 2 K</u> Cables _____ Hawser and Warps <u>4 No (1 new)</u> Standing & Running Rigging _____ | } <u>where</u> } <u>she</u> } <u>could</u> } <u>be</u> } <u>seen</u> } <u>Good</u> |
|---|--|---|---|

General Observations and Opinion, At present bottom cleaned and coated with zinc paint
and Shiff's composition inside where clear of cargo washed with Portland
cement & water - not seen below having inward & outward cargo in - the
is reported to have been cleaned and cemented (Portland cement) at Liverpool
in 1862. (see certificate herewith) she appears good and firm and eligible
in my opinion to continue as classed A 1
 Committee's Minute 14th March 1862

Character assigned 12 A 1 Certificate (if required)



No. _____ Survey held _____ Date _____ 18__
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

| | | | |
|---|---|--|--|
| Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ | Treenails _____ Breasthooks and Stenson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper _____ When put on _____ | Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. _____ Sails _____ Anchors No. of _____ Cables _____ Hawser and Warps _____ Standing & Running Rigging _____ | |
|---|---|--|--|

General Observations and Opinion, _____ Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18__

Character assigned _____



© 2019
 Lloyd's Register
 Foundation
 Certificate (if required)
 IRON435-0340