

2869 Iron REPORT of SURVEY for REPAIRS.

No. 5 Survey held at London Date July 10th 1862
 on the Barge "Haddington" Master Geo Birwne
 Tonnage 459 Built at London When built 1846
 By whom built _____ Owners P & O. Company
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Imp^d Green's Dry Dock

Last Survey, No. 2396 Port Port. Classed Cont^d 6A.1 1858

REPAIRS

Now done, her main mast renewed with Oregon Pine, One new upper deck, and one new lower deck beam added in the fore Hatchways, and the Comings renewed to the fore Hatchways. the bottom coated with two coats of Red Lead and one coat of Peacocks Paint. the main rigging refitted. The Ceiling lifted for the examination of the inside of the plates and rivets. in various parts of the hold. all found satisfactory where seen.

Present Condition of the

Decks	Treenails <u>none</u>	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stenson	Pumps
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons	Sails
Planksheers	Clumps and Shelves } <u>Good where</u>	Anchors No. of
Sheerstrakes } <u>Good where</u>	Ceiling	Cables
Topsides } <u>seen</u>	Rudder	Hawsers and Warps
Wales	Copper <u>none</u> When put on	Standing & Running Rigging
Plank (Bottom) and Counter <u>Painted</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

She is in good and efficient Condition, fit in my opinion to remain as classed Cont^d 6A.1.

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 12th August 1862

Character assigned Cont^d 6A.1

J.S. 1862

IRON435-0491