

ANNUAL SURVEYS.

No. 18333 Survey held at Birkenhead
on the Iron Ship "Thames" Master

Date July 2 18 63

Tonnage 533 Built at Sunderland

When built 1860

By whom built

Owners Bealey & Co.

Port belonging to Liverpool

Destined Voyage Singapore

If Surveyed Afloat or in Dry Dock

Messrs. Clover & Co's Dry Dock

Last Survey, No. 2670

Port of Iron

Classed

12 A 1.
62

The present Condition of the

Decks	good	Treenails		Windlass and Capstan	good
Waterways		Breasthooks and Stemson		Pumps	"
Comings		Transoms, Pointers, and Crutches	Iron	Boats	good and sufficient
Upper Deck Beams & Fastenings	good	Timbers of the Frame	good	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	where	Keelsons	where	Sails	"
Planksheers	seen	Clamps and Shelves	seen	Anchors No. of	"
Sheerstrakes		Ceiling		Cables	"
Topsides		Rudder		Hawsers and Warps	"
Wales		Copper	When put on	Standing & Running Rigging	"
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done, - Bottom painted. This vessel is now in good condition, and in my opinion eligible to remain as Classed 12 A 1.

Committee's Minute

11th September 18 63

Character assigned

12 A 1

Certificate (if required)

No. 820 Survey held at Birkenhead
on the Iron Ship "Gargano" Master

Date August 25 18 63

Tonnage 1163 Built at Port Glasgow

When built 1862

By whom built

Owners J. Dunsell

Port belonging to Liverpool

Destined Voyage Melbourne

If Surveyed Afloat or in Dry Dock

Messrs. Clover & Co's Dry Dock

Last Survey, No. 2882

Port of Iron

Classed

12 A 1.
62

The present Condition of the

Decks	good	Treenails		Windlass and Capstan	good
Waterways		Breasthooks and Stemson		Pumps	"
Comings		Transoms, Pointers, and Crutches	Iron	Boats	good & sufficient
Upper Deck Beams & Fastenings	Iron	Timbers of the Frame	good	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	good	Keelsons	where	Sails	"
Planksheers	where	Clamps and Shelves	seen	Anchors No. of	"
Sheerstrakes	seen	Ceiling		Cables	"
Topsides		Rudder		Hawsers and Warps	"
Wales		Copper	When put on	Standing & Running Rigging	"
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

This vessel is now in good condition. Bottom painted, and in my opinion eligible to remain as Classed 12 A 1.

Committee's Minute

11 September 18 63

Character assigned

12 A 1

Certificate (if required)

1K05436-0444-0301

"Sharpshooter"
"Eurynome" 18333



© 2019

Lloyd's Register

Specialist Surveyors