

ANNUAL SURVEYS.

No. 18449 Survey held at Birkenhead Date Oct 15 1863
 on the Iron Ship Staffordshire Master Cameroon
 Tonnage 1173 Built at Liverpool When built 1862
 By whom built Liverpool Owners Boulton & Co
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Men's Cove's Dry dock

Last Survey, No. 2997 Port of Iron Classed 12 A 1
62

The present Condition of the

Decks <u>good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches	Boats <u>good & sufficient</u>
Upper Deck Beams & Fastenings <u>Iron</u>	Timbers of the Frame <u>Iron</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>good</u>	Clamps and Shelves <u>good Condition</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>Condition</u>	Ceiling	Cables <u>"</u>
Topsides	Rudder	Hawsers and Warps <u>"</u>
Wales	Copper When put on	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. - Bottom painted. - This vessel is now in good condition and in my opinion eligible to remain as Classed 12 A 1

Committee's Minute 13th November 1863

Character assigned 12 A 1

Certificate (if required)

No. 288 Survey held at Birkenhead Date Oct 30 1863
 on the Iron Ship Henry Moore Master Stewart
 Tonnage 1117 Built at Greenock When built 1854
 By whom built Liverpool Owners Moore & Co
 Port belonging to Liverpool Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Woodside Graving Dock

Last Survey, No. 2600 Port of Iron Classed 12 A 1
(1861) 61

The present Condition of the

Decks <u>good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways <u>" Caulked</u>	Breasthooks and Stemson	Pumps <u>"</u>
Comings <u>good</u>	Transoms, Pointers, and Crutches <u>Iron</u>	Boats <u>good and sufficient</u>
Upper Deck Beams & Fastenings <u>Iron</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>Iron</u>	Keelsons <u>where</u>	Sails <u>"</u>
Planksheers <u>good where</u>	Clamps and Shelves <u>seen</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>seen</u>	Ceiling	Cables <u>"</u>
Topsides	Rudder	Hawsers and Warps <u>"</u>
Wales	Copper When put on	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. - Bottom painted. - She is now in good condition and in my opinion eligible to remain as Classed 12 A 1

Committee's Minute 13th November 1863

Character assigned 12 A 1

Certificate (if required)

Staffordshire. —

1844 q.

Henry Moore. —



© 2019

Lloyd's Register
Foundation