

ANNUAL SURVEYS.

No. 241 Survey held at London Date Dec 8th 18 63
 on the S. + Bianca Iron Master Rennie
 Tonnage 138 1/2 Built at Liverpool When built 1862
 By whom built Layrnes Owners Moore & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Wigram's dock &

Last Survey, No. 3005 Port of Liverpool Classed 12 A 1
 12.62

The present Condition of the

Decks		Treenails Rivets		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	<u>Where</u>	Timbers of the Frame at the Openings	<u>Where</u>	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings		Do Do at other places		Sails	
Planksheers	<u>seen</u>	Keelsons		Anchors No. of	<u>4</u>
Sheerstrakes		Clamps and Shelves	<u>seen</u>	Cables	<u>sufficient</u>
Topsides	<u>good</u>	Ceiling	<u>good</u>	Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper When put on			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen good

Lead - Bottom cleaned & covered with three coats of Tallow & Res
This vessel is eligible in my opinion to
remain classed A 1

Committee's Minute 11th December 18 63

Character assigned 12 A 1

Thos W. Hawn

Certificate (if required)

No. 495 Survey held at London Date Oct 19th 18 63
 on the Sea S + Pyhope Master J Douglas
 Tonnage 698 Built at Sunderland When built 1860
 By whom built 473 Owners 14 Taylor
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 2445 Port of Liverpool Classed 9 A 1
 61

The present Condition of the

Decks		Treenails Rivets		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	<u>Where</u>	Timbers of the Frame at the Openings	<u>Where</u>	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings		Do Do at other places		Sails	<u>4</u>
Planksheers	<u>seen</u>	Keelsons		Anchors No. of	<u>sufficient</u>
Sheerstrakes		Clamps and Shelves	<u>seen good</u>	Cables	
Topsides	<u>good</u>	Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Planks		Copper When put on			
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen good

Bottom cleaned and covered with two coats of Zinc paint
on Starboard, and one coat of oxide of Iron, one of black barnish and
one of soap of Lime on port side, to test the relative merits
It is now in good condition and eligible to remain

Committee's Minute 11th December 18 63

Character assigned 9 A 1

Thos W. Hawn

Certificate (if required)