

# ANNUAL SURVEYS.

No. 3441 Survey held at Hull Date 1<sup>st</sup> March 1864  
 on the Iron Steamer "Gertrude" Master J. Wilson  
 Tonnage 608 Built at Hull "Gertrude" When built 1855  
 By whom built 527 Owners Loft & Co  
 Port belonging to Hull Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock On Samuels

Last Survey, No. 3095 Port of Gorn.

Classed GA 1  
(7.5-61) 63

The present Condition of the

Decks <u>Caulked</u>	<u>Keelsons</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>Good</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>at the Openings</u> <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Do Do at other places <u>Good</u>	Sails <u>Good</u>
Planksheers <u>Good</u>	Keelsons <u>Good</u>	Anchors No. of _____
Sheerstrakes <u>Good</u>	Clamps and Shelves <u>Good</u>	Cables _____
Topsides <u>Good</u>	Ceiling <u>Good</u>	Hawsers and Warps _____
Wales <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter <u>Good</u>	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Now done - Bottom turned & coated with paint Deck Caulked  
is eligible in my opinion to remain as classed GA 1

Committee's Minute 11<sup>th</sup> March 1864

Character assigned GA 1

M. Davidson

Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_

on the \_\_\_\_\_ Master \_\_\_\_\_

Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_

By whom built \_\_\_\_\_ Owners \_\_\_\_\_

Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_

If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>at the Openings</u> _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Do Do at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register

Certificate (if required).

120N437-0169