

3640

REPORT of SURVEY for REPAIRS.

Supp 3 No. 3478 Survey held at Gook Date 15th June 1864
on the Br. S^t. Marshland Master John Sales
Tonnage 327 Built at Stettin When built 1863
By whom built Richardson Suck & Co Owners Port of
Port belonging to London Destined Voyage Renew
If Surveyed Afloat or in Dry Dock In dry dock

Last Survey, No. 3322 Port SW. Classed 9 A 1

REPAIRS

Now done Bilge plates fitted on each side for sixty six
feet amidships plates 10 x 9.6 with two angle bars of 3 x 3 x 9.6
Ceiling in way of same lifted and replaced, the rivets being
covered over with cement. Bottom Coated with Paint

Present Condition of the

Decks	<u>Good</u>	Tenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson			
Comings		Transoms, Pointers, and Crutches			
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings			
Lower Deck Beams & Fastenings		Ditto Ditto at other places			
Planksheers		Keelsons			
Sheerstrakes		Clamps and Shelves			
Topsides		Ceiling			
Wales		Rudder			
Plank (Bottom) and Counter		Copper		When put on	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good</u>				

Is eligible in my opinion to remain as Classed 9 A 1

The Amount of Fee.....£ 1 : : is received by me,

Special..... 1 : 1 :

Certificate (if required) : :

Committee's Minute 28th June 18 64

Character assigned 9 A 1

second repair
WMA



© 2019

Lloyd's Register
Foundation

IRON437A-0068