

ANNUAL SURVEYS.

27424

No. 28 Survey held at London Date September 2nd 1864
 on the Br "Napier" (Iron) Master "Petherbridge"
 Tonnage 5 1/2 Built at W. Hartlepool When built 1863
 By whom built _____ Owners Parr Bros
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Wilson Patent Slip

Last Survey, No. 2310 Port of Iron. Classed 12. A. I.
 7.63

The present Condition of the

Decks <u>Good where seen</u>	Rivets <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Do Do at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of <u>Sufficient</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen.
 The bottom of this vessel has now been cleaned and painted;
 she appears to be in good and efficient condition, and
 is eligible, in my opinion, to remain as classed.

Committee's Minute 21st October 1864

Character assigned 12A1

Jos. McWarr

Certificate (if required)

Supp No. Survey held at London Date October 5th 1864
 on the S.S. "Evelyn Mary" (Iron) Master J. McIntire
 Tonnage 5 1/2 Built at Newcastle When built 1864
 By whom built _____ Owners H. Harris
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Grindon, Fountain Dock.

Last Survey, No. _____ Port of _____ Classed A. I.
 0.64.

The present Condition of the

Decks <u>Good where seen</u>	Rivets <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Do Do at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of <u>Sufficient</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen.
 This vessel appears to be in good and efficient
 condition, and is eligible, in my opinion, to remain as classed.

Committee's Minute 21st October 1864

Character assigned B1

Certificate (if required)

IRON 437A-0245