

4009

REPORT of SURVEY for REPAIRS.

Rec 16/3/64

No. 2307 Survey held at Glasgow Date 22nd February 1865
on the Ship City of Perth Master William Cunell
Tonnage 1134 Built at Glasgow When built 1864
By whom built Burley Park & Co Owners George Smith & Sons
Port belonging to Glasgow Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 3545 Port Glasgow Classed A. 1

REPAIRS Fitted Two Angle Bars 5 x 4 1/2 x 9/16 on each side between middle line
and Ridge Keelson extending Fore and Aft for a Length of One Hundred and
five Feet Amidships as Compensation for want of Intermediate Inter-vent
Keelson as per Secretary's Letter of 16th April 1864

Present Condition of the

Decks	<u>Good</u>	Trunnels	<u>Nuts</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breastrocks and Stemson	<u>do</u>		Pumps	<u>do</u>
Timings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>		Boats	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the openings	<u>do</u>		Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto Ditto at other places	<u>do</u>		Sails	<u>do</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>		Anchors	No. of <u>31 Br 1 Stone 2 Wedge</u>
Beerstrakes	<u>Good</u>	Clamps and Shells	<u>do</u>		Cables	<u>Complete</u>
Oppides	<u>do</u>	Ceiling	<u>do</u>		Hawsers and Warps	<u>do</u>
Plates	<u>do</u>	Rudder	<u>do</u>		Standing & Running Rigging	<u>do</u>
Hulk (Bottom) and Counter	<u>do</u>	Copper	<u>When put on</u>			

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways.
Ship in good Condition Eligible in my opinion to remain as Classed

The Amount of Fee.....£ : : is received by me,
Special..... : :
Certificate (if required) : : :

A. Darling

Committee's Minute 17th March 1865

Character assigned W



© 2019
Lloyd's Register
Foundation
IRON 438 0164