

REPORT of SURVEY for REPAIRS.

in Book No. 10374 Survey held at Birkenhead Date April 1 to 8 1865
 on the (Iron) S.S. "Wave Queen" Master Searle
 Tonnage 622 Built at Glasgow When built 1863 - 6mo
 By whom built Wingate Owners W. B. Bott
 Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Great Float graving dock

Last Survey, No. 3785 Port Iron Classed 9. A1
 9. 64

REPAIRS

Bottom scraped & coated with red lead, the
 Ceiling lifted inside ^{at timbers} for examination of the surfaces of iron
 & rivets - the same found good; after hatchway enlarged,
 & gangway ports cut in bulwarks abreast of fore and after
 hatchways.

Present Condition of the

Decks	<u>good</u>	Treenails		Windlass and Capstan	<u>good & efficient</u>
Waterways	"	Breasthooks and Stemson		Pumps	" "
Omings	"	Transoms, Pointers, and Crutches		Boats	" "
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	<u>good</u>	Masts, Yards, &c.	" "
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Sails	" "
Plank sheers	"	Keelsons	"	Anchor No. of	" "
Sheerstrakes	"	Clamps and Shelves		Cables	" "
Topsides		Ceiling	"	Hawsers and Warps	" "
Wales		Rudder	"	Standing & Running Rigging	" "
Plank (Bottom) and Counter		Copper	When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Satisfactory

Is now in an efficient condition & in my opinion
eligible to remain as Classed

The Amount of Fee Paid, in London, £ / : " : " is received by me,

Special... 2 : 2 : " } 3/5/65

Certificate (if required) " : 5 : "

Committee's Minute Liverpool, 5th May 1865

Character assigned 9 A1

W. B. Bott
 © 2019
 Lloyd's Register
 Foundation

IRON 438-0247

Wave Queen
19374. -



© 2019

Lloyd's Register
Foundation