

ANNUAL SURVEYS.

Iron.

2785

No. 74 Survey held at London Date June 15th to July 3rd 1865.

on the Br. + "Adamant" (Iron) Master

Tonnage 215 Built at Hull When built 1858

By whom built Owners Harrison

Port belonging to London Destined Voyage

If Surveyed Afloat or in Dry Dock Horseferry Dock

Last Survey, No. 3705 Port of Iron.

Classed 12. A. I. t. S. - 64. 6. 64.

The present Condition of the

Decks Good where seen

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Plank (Bottom) and Counter "

Rivets Good where seen

Breasthooks and Stemson "

Transoms, Pointers, and Crutches "

Frames of the Frames at the Openings "

Keelsons Do at other places "

Clamps and Shelves "

Ceiling "

Rudder "

Copper When put on

Windlass and Capstan Good

Pumps "

Boats "

Masts, Yards, &c. "

Sails "

Anchors No. of Sufficient

Cables "

Hawsers and Warps "

Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

The bottom has now been cleaned and painted; she appears to be in good & efficient condition, and eligible, in our opinion, to remain as classed - 12. A. I.

Committee's Minute 11th July 1865

Character assigned 12 A I MT

R. J. Reed.

J. W. Kettle

Certificate (if required)

No. 22 Survey held at London Date May 15th 1865.

on the Br. + "Eagle" (Iron) Master

Tonnage 392 Built at London When built 1859

By whom built Owners Houlay, Campbell & Co.

Port belonging to London Destined Voyage

If Surveyed Afloat or in Dry Dock King & Queen Dry Dock.

Last Survey, No. 3575 Port of Iron.

Classed 9. A. I. t. S. - 63. 2. 63.

The present Condition of the

Decks Good where seen

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Plank (Bottom) and Counter "

Rivets Good where seen

Breasthooks and Stemson "

Transoms, Pointers, and Crutches "

Frames of the Frames at the Openings "

Keelsons Do at other places "

Clamps and Shelves "

Ceiling "

Rudder "

Copper When put on

Windlass and Capstan Good

Pumps "

Boats "

Masts, Yards, &c. "

Sails "

Anchors No. of Sufficient

Cables "

Hawsers and Warps "

Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

The bottom has now been cleaned and painted; she appears to be in good and efficient condition, and eligible, in our opinion, to remain as classed - 9. A. I.

Committee's Minute 11th July 1865

Character assigned 9 A I MT

R. J. Reed

J. W. Kettle

Certificate (if required).

IRON438-0325