

ANNUAL SURVEYS.

No. 210 Survey held at London Date May 17th 1865
 on the Iron Screw Ship Elamie Master Rose
 Tonnage 593 Built at Meidalesboro When built 1864
 By whom built Cyndlish Owners G. Matthew
 Port belonging to Sunderland Destined Voyage
 If Surveyed Afloat or in Dry Dock Ratcliffe Cross Dock

Last Survey, No. 3946 Port of Iron Classed B I
1, 65

The present Condition of the

Decks Good when seen
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings "
 Lower Deck Beams & Fastenings "
 Planksheers Scraped and
 Sheerstrakes Painted
 Topsides "
 Wales "
 Plank (Bottom) and Counter "

~~Freemasts~~ Ports good when seen
 Breasthooks and Stenson "
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings "
 Keelsons Do Do at other places "
 Clamps and Shelves "
 Ceiling "
 Rudder 2 Hats Red Lead
 When put on Now

Windlass and Capstan Good
 Pumps Sufficient
 Boats "
 Masts, Yards, &c. Good
 Sails Sufficient
 Anchors No. of "
 Cables "
 Hawasers and Warps "
 Standing & Running Rigging Good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good when seen

This vessel appears to be in good condition and eligible in our opinion to remain as classed.

Committee's Minute 11th July 18 65

Character assigned B I

J. H. Riddle.
John Maxwell

Certificate (if required)

No. 8 Survey held at London Date 27th Mar. to 31st Mar 1865
 on the Iron Ship Oberon Master H. Powell
 Tonnage 1181 Built at Port Glasgow When built 1864
 By whom built Reid Owners Powell & Co
 Port belonging to Liverpool Destined Voyage Bamby
 If Surveyed Afloat or in Dry Dock Ratcliffe Cross Dock

Last Survey, No. 3513 Port of Iron Classed A I
64

The present Condition of the

Decks Good when seen
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings "
 Lower Deck Beams & Fastenings "
 Planksheers Scraped and
 Sheerstrakes Painted
 Topsides "
 Wales "
 Plank (Bottom) and Counter "

~~Freemasts~~ Ports good when seen
 Breasthooks and Stenson "
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings "
 Keelsons Do Do at other places "
 Clamps and Shelves "
 Ceiling "
 Rudder 2 Hats Red Lead
 When put on Now

Windlass and Capstan Good
 Pumps Sufficient
 Boats "
 Masts, Yards, &c. Good
 Sails Sufficient
 Anchors No. of "
 Cables "
 Hawasers and Warps "
 Standing & Running Rigging Good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good when seen

This vessel appears to be in good condition and eligible in our opinion to remain as classed.

Committee's Minute 11th July 18 65

Character assigned A I

J. H. Riddle
John Maxwell

Certificate (if required).