

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 329 Survey held at London Date July 5th to 12th 18 63
 on the Ship "Sea Queen" Master Cunningham
 Tonnage 873 Built at Glasgow When built 1838
 By whom built _____ Owners J. Allan &
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Union Dry Dock & East India Dock

Last Survey, No. 3012 Port Iron. Classed 12 1/2 1.
 62

REPAIRS

How done, Scraped and Painted, and the bottom finally coated with Tallow -
 Ceiling lifted in the fore and after hold and the condition of the plating and rivets & found to be in good condition where seen -
 The Hawse Pipe on the port side and the Rudder Braces renewed - the steering gear put into good order -

Present Condition of the

Decks	} <u>Good</u>	Treenails	<u>None</u>	Windlass and Capstan	
Waterways		Breasthooks and Stenson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} <u>Good</u>	Timbers of the Frame at the openings		Masts, Yards, &c.	<u>Good and</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	<u>Sufficient</u>
Planksheers	} <u>Good</u>	Keelsons	<u>Good</u>	Anchors No. of	
Sheerstrakes		Clamps and Shelves	<u>Where seen</u>	Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter	<u>Good</u>	Copper	<u>None</u> When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen -

She is now in good condition, fit in my opinion to remain as classed 12 1/2 1. and to be marked in the Register Book L.S. 65 -
B. D. Raymond

The Amount of Fee.....£ : : is received by me,

Special..... / : / : -

Certificate (if required) : 5 : -

Committee's Minute 15th August 18 65

Character assigned 12 1/2 1
 (L.S. 65)



© 2019

Lloyd's Register Foundation

IRON438-0409