

on Ships

ANNUAL SURVEYS.

27051

No. Survey held at London Date July 13th 1865
 on the Steamer "Alexandra" Master W. Russell
 Tonnage 813 Built at London When built 1863
 By whom built Thames Iron Works Owners Lon. Ital. & Adc. S. N. Co.
 Port belonging to London Destined Voyage Lon & Mediterranean
 If Surveyed Afloat or in Dry Dock Dorsifery Dry Dock

Recd 2/10/65

Last Survey, No. 3241 Port of Iron Classed 9 A.1.
 8.63

Present Condition of the

Deck Beams & Fastenings Deck Beams & Fastenings Sides Counter	} good where seen Painted	Treennails Rivets Breasthooks and Stimson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Do Do at other places Keelsons Clamps and Shelves Ceiling Rudder Copper Paint When put on <u>now</u>	} good where seen when seen	Windlass and Capstan Pumps Boats Masts, Yards, &c. Sails Anchors No. of Cables Hawers and Warps Standing & Running Rigging	} good and sufficient when seen
--	--	---	---	--	---

Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
done. The bottom scraped and painted - She is now in
good and efficient condition fit in my opinion to remain
as classed 9 A.1.
6th October 1865
9 A.1
Stornish
 Certificate (if required)

No. Survey held at London Date Sep 5th & 28th 1865
 on the Ship "Himalaya" Master C. B. Low
 Tonnage 1008 Built at Sunderland When built 1863
 By whom built Pile Owners G. D. Tyer
 Port belonging to London Destined Voyage New Zealand & India
 If Surveyed Afloat or in Dry Dock Youngs Dry Dock & East India Dock

Last Survey, No. 3445 Port of Iron Classed A.1.
 1263

Present Condition of the

Deck Beams & Fastenings Deck Beams & Fastenings Sides Counter	} good where seen 2	Treennails Rivets Breasthooks and Stimson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Do Do at other places Keelsons Clamps and Shelves Ceiling Rudder Copper Paint When put on <u>now</u>	} good where seen when seen	Windlass and Capstan Pumps Boats Masts, Yards, &c. Sails Anchors No. of Cables Hawers and Warps Standing & Running Rigging	} good and efficient when seen
--	--	---	---	--	--

Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
now done, The bottom scraped and painted with white Zinc -
to ceiling lifted from the bilge keelson to bilge keelson and the
bottom re-cemented with Portland Cement - and all the inside
work cleaned and painted - She is now in good condition, fit
in my opinion to remain as classed A.1.
6th October 1865
A.1
Stornish
 Certificate (if required)

