

ANNUAL SURVEYS.

(Iron)

No. 400 Survey held at London Date Nov 9th to 10th 1865
 on the S.S. + John Hewick (now) Master H. Greig
 Tonnage 699 Built at Newcastle When built 1861
 By whom built J. Hewick Owners J. Hewick
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Victoria Dock.

Last Survey, No. 3811

Port of Iron.

Classed

6. A. 1.
(t.s. 65) 3. 65.

The present Condition of the

Decks Good & pt new
 Waterways good where seen
 Comings "
 Upper Deck Beams & Fastenings "
 Lower Deck Beams & Fastenings "
 Planksheers "
 Sheerstrakes "
 Topsides "
 Wale "
 Plank (Bottom) and Counter "

Risks
Good where seen
 Breasthooks and Stemson "
 Transoms, Pointers, and Crutches "
~~Members of the Frame~~ at the Openings "
 Do at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder "
~~Copper~~ When put on

Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Sails Sufficient
 Anchors No. of "
 Cables "
 Hawsers and Warps "
 Standing & Running Rigging "

General Observations and Opinion

Caulking of Bottom, Deck, and Waterways

Good where seen
 This vessel has now had her rollers removed, and has been examined in way of them; some few rivets renewed, and the beams repaired; she appears to be in good condition, and eligible, in my opinion, to remain as classed.

R. J. Reed

Committee's Minute 15th December 1865

Character assigned A 1

Certificate (if required)

No. 570 Survey held at London Date Oct 28th to Nov 2nd 1865
 on the S.S. "Aminta" (now) Master Maxted
 Tonnage 1132 Built at Liverpool When built 1862
 By whom built Owners Moore & Co.
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Wigram's Dry Dock.

Last Survey, No. 3940

Port of Iron.

Classed

A. 1.
(S. S. No. 1-64) 12. 64.

The present Condition of the

Decks Good where seen
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings "
 Lower Deck Beams & Fastenings "
 Planksheers "
 Sheerstrakes "
 Topsides "
 Wale "
 Plank (Bottom) and Counter "

Risks
Good where seen
 Breasthooks and Stemson "
 Transoms, Pointers, and Crutches "
~~Members of the Frame~~ at the Openings "
 Do at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder "
~~Copper~~ When put on

Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Sails Sufficient
 Anchors No. of "
 Cables "
 Hawsers and Warps "
 Standing & Running Rigging "

General Observations and Opinion

Caulking of Bottom, Deck, and Waterways

Good where seen
 This vessel's bottom has now been scraped & painted. She appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

R. J. Reed

Committee's Minute 15th December 1865

Character assigned A 1

Certificate (if required).