

# REPORT of SURVEY for REPAIRS.

& Triennial Survey

No. in Reg. Book. **No.** 373 Survey held at London Date June 23<sup>rd</sup> 1865  
 on the Schooner "London" Master W. G. Hall  
 Tonnage 1013 Built at Newcastle When built 1862  
 By whom built \_\_\_\_\_ Owners W Wood  
 Port belonging to London Destined Voyage Mediterranean  
 If Surveyed Afloat or in Dry Dock Union dry dock & London Dock

Last Survey, No. 3813 Port Gen. Classed G A 1  
 64

## REPAIRS

In dry dock the outside cleaned and painted with three coats (one of Red Lead) the ceiling in two of the holds lifted and the cement and inside found in good condition.

(voluntarily by the owner)  
 Added, six extra beams to lower deck, and two pairs of half beams.

In London Dock

The ceiling in the remaining holds lifted and every thing found in good condition

## Present Condition of the

Decks		Trunnels Rivets		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	Good	Ditto Ditto at other places	Good	Condition, how ascertained	Good and sufficient
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper When put on		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

This vessel is now in good and efficient condition and is eligible in my opinion to remain classed G A 1

The Amount of Fee.....£..... is received by me, and be marked T.S. 65

Special..... 2: 2: -  
 Certificate (if required) - : 5: -

Committee's Minute 9<sup>th</sup> January 1866

Character assigned G A 1  
 (t.s. 65)

Thos. W. Hawn



Lloyd's Register Foundation

180439-0097