

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 4491 Survey held at London Date Dec<sup>r</sup> 16<sup>th</sup> 18 65  
 on the S<sup>r</sup> Star of Scotia Master D. Mc Dowell  
 Tonnage 999 Built at Belfast When built 1864  
 By whom built Harland Owners Ferry & Sons  
 Port belonging to Belfast Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock in Wigan's & East India Docks

Last Survey, No. 3927 Port Iron Classed A 1  
12.64

## REPAIRS

Scraped and painted bottom with two coats of oxide of iron paint and two of Peacocks paint.

| Present Condition of the          |             |  |                        |  |             |
|-----------------------------------|-------------|--|------------------------|--|-------------|
| Decks                             | <u>Good</u> | <del>Greenails</del> <u>Rivets</u>     | <u>Good</u>            | Windlass and Capstan   | <u>Good</u> |
| Waterways                         | <u>"</u>    | Breasthooks and Stemson                | <u>"</u>               | Pumps  | <u>"</u>    |
| Comings                           | <u>"</u>    | Transoms, Pointers, and Crutches       | <u>"</u>               | Boats  | <u>"</u>    |
| Upper Deck Beams & Fastenings     | <u>"</u>    | Timbers of the Frame at the openings   | <u>"</u>               | Masts, Yards, &c.  | <u>"</u>    |
| Lower Deck Beams & Fastenings     | <u>"</u>    | Ditto Ditto at other places            | <u>"</u>               | Condition, how ascertained <u>from enquiry &amp; as seen from deck</u> |             |
| Planksheers                       | <u>"</u>    | Keelsons <u>Not seen</u>               | <u>"</u>               | Sails  | <u>"</u>    |
| Sheerstrakes                      | <u>"</u>    | Clamps and Shelves                     | <u>"</u>               | Anchors No. of <u>3 B, 1 S, 2 K</u>                                    |             |
| Topsides                          | <u>"</u>    | Ceiling <u>where seen</u>              | <u>"</u>               | Cables   | <u>"</u>    |
| Wales                             | <u>"</u>    | Rudder                                 | <u>"</u>               | Hawsers and Warps  | <u>"</u>    |
| Plank (Bottom) and Counter        | <u>"</u>    | Copper <u>✓</u> When put on <u>✓</u>   |                        | Standing & Running Rigging   | <u>"</u>    |
| General Observations and Opinion, |             | Caulking of Bottom, Deck, & Waterways. | <u>where seen Good</u> |  |             |

Is now in good and efficient condition and is in my opinion fit to remain as classed.

The Amount of Fee.....£..... is received by me, John Maxwell  
 Special.....:.....

Certificate (if required) : :

Committee's Minute 16<sup>th</sup> January 18 66

Character assigned A 1  
as P. form 40  
Belfast



© 2019  
 Lloyd's Register  
 Foundation  
 IRON 439-0116