

ANNUAL SURVEYS.

(Iron)

2727D

No. 4 Survey held at London Date February 15th 1866
 on the S.S. "Kaffaria" (Iron) Master Cummings
 Tonnage 779 Built at Sunderland When built 1864
 By whom built Loring Owners Diamond Steam Navigation Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock.

Last Survey, No. 4182 Port of Iron Classed C.A.T.
 6.65.

The present Condition of the		Breasts		Windlass and Capstan	
Decks	<u>Good where seen</u>	Breasthooks and Stemson	<u>Good where seen</u>	Pumps	<u>Good</u>
Waterways	"	Transoms, Pointers, and Crutches	"	Boats	"
Comings	"	Frames at the Openings	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Keelsons	Do at other places	Sails	<u>Sufficient</u>
Lower Deck Beams & Fastenings	"	Clamps and Shelves	"	Anchors No. of	"
Planksheers	"	Ceiling	"	Cables	"
Sheerstrakes	"	Rudder	"	Hawsers and Warps	"
Topsides	"	Copper	<u>When put on</u>	Standing & Running Rigging	"
Wales	"				
Plank (Bottom) and Counter	"				

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen
The bottom has now been scraped and painted: she appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.
R. F. Reed

Committee's Minute 23rd February 1866

Character assigned A1

Certificate (if required)

No. 20 Survey held at London Date February 15th 19th 1866
 on the B.R. "Napier" Master Petherbridge
 Tonnage 542 Built at West Hartlepool When built 1863
 By whom built Pile Owners Barth Bros
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 3815 Port of Iron Classed A.T.
 7.64.

The present Condition of the		Breasts		Windlass and Capstan	
Decks	<u>Good where seen</u>	Breasthooks and Stemson	<u>Good where seen</u>	Pumps	<u>Good</u>
Waterways	"	Transoms, Pointers, and Crutches	"	Boats	"
Comings	"	Frames at the Openings	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Keelsons	Do at other places	Sails	<u>Sufficient</u>
Lower Deck Beams & Fastenings	"	Clamps and Shelves	"	Anchors No. of	"
Planksheers	"	Ceiling	"	Cables	"
Sheerstrakes	"	Rudder	"	Hawsers and Warps	"
Topsides	"	Copper	<u>When put on</u>	Standing & Running Rigging	"
Wales	"				
Plank (Bottom) and Counter	"				

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen
The bottom has now been scraped and painted: she appears to be in good and efficient condition and eligible, in my opinion, to remain as classed.
R. F. Reed

Committee's Minute 23rd February 1866

Character assigned A1

Certificate (if required)