

ANNUAL SURVEYS.

32 No. Survey held at London Date 12th to 19th February 1866
 on the Iron Barque "Unicorn" Master Robert Horn
 Tonnage 403 Built at Stockton When built 1863 (19 mo)
 By whom built Richardson Owners Jillispio & Co
 Port belonging to London Destined Voyage Ascension
 If Surveyed Afloat or in Dry Dock Youngs Dry Dock

Last Survey, No. 3364 Port of Iron Classified 12.A.1
AFCP 63

The present Condition of the

Decks	} <u>Good</u>	Treenails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings	} <u>where</u>	Transoms, Pointers, and Crutches	} <u>where</u>	Boats <u>3 7/8</u>	} <u>and</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	<u>Ditto</u> ditto at other places	} <u>where</u>	Sails	} <u>sufficient</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes	} <u>Painted</u>	Clamps and Shelves	} <u>where</u>	Cables	} <u>where</u>
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		<u>Copper</u> <u>Paint</u> When put on <u>now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

Scraped and painted the Bottom and Topsides with
three coats of Patent Varnish. She is now in good and
 efficient condition, and fit, in my opinion, to remain
as fitted.

Committee's Minute 24 February 1866

Character assigned 12.A.1

J. Williamson

Certificate (if required)

No. Survey held at Date 18
 on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classified

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plunk (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18

Character assigned



© 2019

Certificate (if required).

IRON 439 - 0203