

ANNUAL SURVEYS.

5747

H 746 Iron

No. 102 Survey held at London Date 17th to 23rd May 1866
 on the Iron Barque "Merle" Master James Hamilton
 Tonnage 281 Built at London When built 1863 (11 mo.)
 By whom built Westwood Owners Scrutton Sons & Co.
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Limekiln Dry Dock and West India Dock

Last Survey, No. 4285 Port of Iron.

Classed A 1 8-65.

The present Condition of the

Decks	Firmo - } Good	Transoms Rivets	Breasthooks and Stems } Good	Windlass and Capstan	Two - } Good
Waterways		Transoms, Pointers, and Crutches		Boats	
Comings	where	Timbers of the Frame at the Openings	where	Masts, Yards, &c.	and
Upper Deck Beams & Fastenings		Keelsons Do at other places		Sails	
Lower Deck Beams & Fastenings	Scraped	Clamps and Shelves	seen	Anchors No. of 3 B. 15. 2 K	where
Planksheers		Ceiling		Cables	
Sheerstrakes	and seen	Rudder	seen	Hawsers and Warps	seen
Topsides		Copper Painted When put on now		Standing & Running Rigging	
Wales	Painted				
Plank (Bottom) and Counter	Scraped and painted				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways food where seen.

Scraped and painted the Bottom with a mixture of
 coal-tar, Naptha and Lime, - and one of Gallon.
 She is now in good and efficient condition, and fit,
 in my opinion, to remain as classed.

Committee's Minute 25 May 1866

Character assigned A 1

Williamson.

Certificate (if required)

No. 14 Supp. Survey held at London Date 21st May 1866.
 on the Iron Sloop S. "Magna Charta" Master Luke Hubback
 Tonnage 764 Built at Newcastle When built 1865 (3 mo.)
 By whom built Palmer Owners J. Glenwick
 Port belonging to Newcastle Destined Voyage Coast
 If Surveyed Afloat or in Dry Dock Limekiln Dry Dock

Last Survey, No. 4136 Port of Iron.

Classed C 1 6-65.

The present Condition of the

Decks	Firmo - } Good	Transoms Rivets	Breasthooks and Stems } Good	Windlass and Capstan	Two - } Good
Waterways		Transoms, Pointers, and Crutches		Boats	
Comings	where	Timbers of the Frame at the Openings	where	Masts, Yards, &c.	and
Upper Deck Beams & Fastenings		Keelsons Do at other places		Sails	
Lower Deck Beams & Fastenings	Scraped	Clamps and Shelves	seen	Anchors No. of 3 B. 15. 2 K	where
Planksheers		Ceiling		Cables	
Sheerstrakes	and seen	Rudder	seen	Hawsers and Warps	seen
Topsides		Copper Painted When put on now		Standing & Running Rigging	
Wales	Painted				
Plank (Bottom) and Counter	Scraped and painted				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways food where seen.

Scraped and painted the Bottom with two coats of red lead
 paint and one of Gallon. - Caulked the whole of the upper and poop
 decks. - She is now in good and efficient condition and
 fit in my opinion, to remain as
 classed.

Committee's Minute 25 May 1866

Character assigned A 1

Williamson.

Certificate (if required)