

4763

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 3651** Survey held at Hull Date 2nd May 18 66
 277 on the Iron Ste. Sh. Albion Master Soulby
 Tonnage 900 Built at Hull When built 1861
 By whom 769 built Samuelson Owners Wilson & Co
 Port belonging to Hull Destined Voyage Baltic
 If Surveyed Afloat or in Dry Dock In Humphreys dry dock

Last Survey, No. 3429 Port Iron. Classed 9 A 1
 (1863). 12.63

REPAIRS

Now done - The bottom cleaned and painted. Several planks of ceiling in holds lifted and relaid. The work appears in good condition. Deck caulked -

The owners intend lifting the entire ceiling and cementing the flat inside first favorable opportunity. Copy of letter received attached to report -

Present Condition of the

Decks	Good when seen	Transoms	Good when seen	Windlass and Capstan	Good and sufficient
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper When put on		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Apprentice

Is in good condition and under the circumstances stated by Messrs Wilson & Co by, the ceiling to be lifted in a few months. I am of opinion the vessel may be favorably considered for her present character ~~and~~ this survey not being recorded

The Amount of Fee.....£ - - is received by me,

Special..... - -

Certificate (if required) - -

Committee's Minute 8th May 18 66

Character assigned Deferred



© 2019

Lloyd's Register Foundation

IRON 439-0387