

# ANNUAL SURVEYS.

No. 20033 Survey held at Liverpool Date 13<sup>th</sup> and 25<sup>th</sup> June 1866  
 on the Iron Ship British Nation Master  
 Tonnage 1326 Built at Dublin When built 1865  
 By whom built British S. C. C. & Y. Owners British S. C. C. & Y.  
 Port belonging to Liverpool Destined Voyage Liv  
 If Surveyed Afloat or in Dry Dock Sandwich Leaving Dock

Last Survey, No. 4141 Port of Liver Classed A1 6. 65-

## The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>at the openings</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Bottom Coated</u> Copper <u>When put on</u>	Standing & Running Rigging
Bottom and Counter		

## General Observations and Opinion,

## Caulking of Bottom, Deck, and Waterways

This ship is in good and efficient condition, eligible to remain as classed A1

Committee's Minute Liverpool 13<sup>th</sup> July 1866

Character assigned A1

Certificate (if required)

No. 14 Survey held at Liverpool Date 3<sup>rd</sup> & 4<sup>th</sup> July 1866  
 on the Iron Ship Sahara Master Beggs  
 Tonnage 1316 Built at Newcastle When built 1863  
 By whom built 1863 Owners Augs. Egyptian S. M. Co.  
 Port belonging to London Destined Voyage Liv  
 If Surveyed Afloat or in Dry Dock Sandwich Leaving Dock

Last Survey, No. 3770 Port of Liver Classed A1 "Spm-decked" 7. 64

## The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Bottom Coated</u> Copper <u>When put on</u>	

## General Observations and Opinion,

## Caulking of Bottom, Deck, and Waterways

This ship is in good and efficient condition, eligible to remain as classed A1

Committee's Minute Liverpool 13<sup>th</sup> July 1866

Character assigned A1

Certificate (if required)



IRON 439-0418

"British Nation"  
-20055-  
"Lahara"



© 2019

Lloyd's Register  
Foundation