

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 4849 Survey held at London Date August 7<sup>th</sup> 1865  
 on the S. S. Europa (Iron) Master Partridge  
 Tonnage 666 Built at Newcastle When built 1862  
 By whom built \_\_\_\_\_ Owners London S. N. Comp  
 Port belonging to London Destined Voyage Mediterranean  
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock & London Dock

Last Survey, No. 4848 ~~3927~~ Port Iron Classed G A 1

## REPAIRS

The ceiling lifted and the bottom examined, the plating cleaned and painted, and all found in good condition.

## Present Condition of the

Decks	Greenails	Rivets	Windlass and Capstan
Waterways	Breasthooks and Stemson		Pumps
Comings	Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings		Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings <u>Good where</u>	Ditto Ditto at other places <u>Good</u>		Sails <u>sufficient</u>
Planksheers <u>seen</u>	Keelsons <u>where seen</u>		Anchors No. of _____
Sheerstrakes	Clamps and Shelves		Cables
Topsides	Ceiling		Hawsers and Warps
Wales	Rudder		Standing & Running Rigging
Plank (Bottom) and Counter	Copper	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where seen

This vessel is now in good condition and is eligible in my opinion to remain classed A 1 and be marked

The Amount of Fee.....£ \_\_\_\_\_ is received by me,

Z. S. 65

Special..... 2 : 2 : - 14/8/66

Certificate (if required) \_\_\_\_\_

Committee's Minute 14<sup>th</sup> August 18 66

Character assigned G A 1 (to S. 65)



© 2019

Lloyd's Register Foundation

IRON 439-0475