

5742 (Iron)
ANNUAL SURVEYS.

27715

No. 485 Survey held at London Date Aug 20 18 66
on the V.S.S. "Ella Constance" Master Vivian
Tonnage 535 Built at Stenton When built 1858
By whom built Owners Ind & Co
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Bullhead Dock.

Last Survey, No. 4501 Port of Iron. Classified J. A. I. (t.S. 66.) 1.66.

The present Condition of the		Rocks <u>Good where seen</u>		Windlass and Capstan <u>Good</u>	
Decks <u>Good where seen</u>		Transoms		Pumps	"
Waterways	"	Breasthooks and Stemson	"	Boats	"
Comings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Timbers of the Frames at the Openings	"	Sails	<u>Sufficient</u>
Lower Deck Beams & Fastenings	"	Planks ditto at other places	"	Anchors No. of	"
Planksheers	"	Keelsons	"	Cables	"
Sheerstrakes	"	Clamps and Shelves	"	Hawsers and Warps	"
Topsides	"	Ceiling	"	Standing & Running Rigging	"
Wales	"	Rudder	"		
Plank (Bottom) and Counter	"	Copper When put on			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

The bottom has now been cleaned and painted; she appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

N. J. Reed.

Committee's Minute 14 September 18 66

Character assigned 9/21

Certificate (if required)

No. 329 Survey held at London Date August 23rd 18 66.
on the V.S.S. "Blonde" Master B. Woolcot
Tonnage 610 Built at London When built 1863.
By whom built Lungley Owners Gen. Sir John Collier & Co
Port belonging to London Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock Upper Globe Dock.

Last Survey, No. 4701 Port of Iron. Classified O. A. I. 11.65.

The present Condition of the		Rocks <u>Good where seen</u>		Windlass and Capstan <u>Good.</u>	
Decks <u>Good where seen</u>		Transoms		Pumps	"
Waterways	"	Breasthooks and Stemson	"	Boats	"
Comings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Timbers of the Frames at the Openings	"	Sails	<u>Sufficient</u>
Lower Deck Beams & Fastenings	"	Planks ditto at other places	"	Anchors No. of	"
Planksheers	"	Keelsons	"	Cables	"
Sheerstrakes	"	Clamps and Shelves	"	Hawsers and Warps	"
Topsides	"	Ceiling	"	Standing & Running Rigging	"
Wales	"	Rudder	"		
Plank (Bottom) and Counter	"	Copper When put on			

General Observations and Opinion

Caulking of Bottom, Deck, and Waterways

Two plates on Port bow (2nd below Shearstrake) renewed, and bottom cleaned & painted: she appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

N. J. Reed.

Committee's Minute 14 September 18 66

Character assigned 10/21

Thos. W. Wainwright
Certificate (if required).