

# REPORT of SURVEY for REPAIRS.

Rec 24/9/60

No. in Reg. Book. **No. 2527** Survey held at Renfrew Date 14 Sept 1866  
 on the SS S. S. Cassin Master Cuthbertson  
 Tonnage 354 Built at Dumbarton When built 1855  
 By whom built 292 Owners J. Hutchinson  
 Port belonging to Glasgow Destined Voyage Bordeaux  
 If Surveyed Afloat or in Dry Dock Afloat at Renfrew & Ltd. Magazines Patent Ship.

Last Survey, No. 4301 Port Groar Classed 9 A 65 (9.5 65)  
 (out 64-5-65)

REPAIRS Engines and Boilers taken out, broke out Cement under ditto  
Boiled the Plating in several places found not to have  
sustained any perceptible diminution. Now fitted with  
new Engines and Boilers. Bottom coated with Red Lead  
and one Coat of the same Patent Paint.

## Present Condition of the

|  |  |  |
|--|--|--|
| Decks <u>Good where seen</u>           | Rivets <u>Good where seen</u>                            | Windlass and Capstan <u>Good</u>                 |
| Waterways <u>"</u>                     | Freemails <u>"</u>                                       | Pumps <u>"</u>                                   |
| Comings <u>"</u>                       | Breasthooks <u>"</u>                                     | Boats <u>"</u>                                   |
| Upper Deck Beams & Fastenings <u>"</u> | <del>Keelsons</del> <u>Porters and Crutches</u> <u>"</u> | Masts, Yards, &c. <u>Good &amp; in condition</u> |
| Lower Deck Beams & Fastenings <u>"</u> | <u>Timbers of the Frame at the openings</u> <u>"</u>     | Condition, how ascertained <u>by Enquiry</u>     |
| Planksheers <u>"</u>                   | Ditto Ditto at other places <u>"</u>                     | Sails <u>Sufficient</u>                          |
| Sheerstrakes <u>"</u>                  | Keelsons <u>"</u>  | Anchors No. of <u>3 Bow 1 Stern 2 Red</u>        |
| Topsides <u>"</u>                      | Clamps <u>and Stays</u> <u>"</u>                         | Cables <u>Complete</u>                           |
| Wales <u>"</u>                         | Ceiling <u>"</u>   | Hawsers and Warps <u>"</u>                       |
| Plank (Bottom) and Counter <u>"</u>    | Rudder <u>"</u>  | Standing & Running Rigging <u>"</u>              |
|  | Copper <u>✓</u> <u>Where not on</u>                      |  |

## General Observations and Opinion,

## Caulking of Bottom, Deck, & Waterways.

Good where seen.  
Appears to be in good and efficient condition and fit  
in my opinion to remain as Classed

The Amount of Fee.....£ 4 : 0 : 0 is received by me.

Special.....£ 1 : 1 : 0

Certificate (if required).....£ 0 : 0 : 0

Committee's Minute 25<sup>th</sup> September 1866

Character assigned 9 A 1

J. H. Little



© 2019

Lloyd's Register  
 Foundation

IRON440-0078