

5086
Iron Ship

27758

REPORT of SURVEY for REPAIRS.

No. in Book. **No.** Survey held at London Date Sept 18th 20th 1866
on the Iron S.S. "James Price" Master G. Morrill
Tonnage 695 Built at Newcastle When built 1863
By whom built Palmer Owners J. Fenwick
Port belonging to London Destined Voyage Newcastle
If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 4740 Port Iron Ships Classed 6A.1
4766

REPAIRS

now done. Several butts of the bottom plating caulked. and a few of the rivets renewed - and the bottom scraped and painted with two coats of Red lead and one of Tallow

Present Condition of the

Decks	} good	Treenails	} good	Windlass and Capstan	} good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Plank sheers	} where	Keelsons	} where	Sails	} efficient
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper Paint When put on now		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good and efficient condition, fit in our opinion to remain as classed 6A.1, and to be marked in the Register Book. (t.s. 1866) the triennial survey having been complied with in April 1866. See Report no 4740

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required)

Committee's Minute 28th September 1866

Character assigned 6A.1
(t.s. 1866)

G. Morrill



© 2019

Lloyd's Register Foundation

IRON 440 0086