

ANNUAL SURVEYS.

66 No. 1177 Survey held at London Date Sept 24th 18 66
 on the S. James Swesey Master Walton
 Tonnage 1072 Built at Liverpool When built 1857
 By whom built Owners Potter Bros
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock in Union & East India Docks

Last Survey, No. 4290 Port of Iron.

Classed A1
 SS No 2. 64 65

The present Condition of the

Decks when seen Good	Treenails Rivets when seen Good	Windlass and Capstan Good
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of 3 B, 1 S, 1 K.
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways when seen Good

Painted inner surfaces of plating from Bilges to Lower deck stringer, also bottom
 Is now in good and efficient condition and is in my opinion fit to remain
 as classed.

Committee's Minute 25th September 18 66

Character assigned

A 1 M

John Maxwell

Certificate (if required)

876 No. 1177 Survey held at London Date Sept 24th 18 66
 on the Bk Merle Master Hamlyn
 Tonnage 281 Built at London When built 1863
 By whom built Westwood Owners Scullion Sons & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock in Union & West India Docks

Last Survey, No. 4746 Port of Iron.

Classed A1
 5.65

The present Condition of the

Decks when seen Good	Treenails Rivets when seen Good	Windlass and Capstan Good
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of 3 B, 1 S, 2 K.
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways when seen Good

Scraped, and painted bottom with Coal Tar and Naptha.
 Is now in good and efficient condition and is in my opinion fit to remain
 as classed.

Committee's Minute 25th September 18 66

Character assigned

A 1 M

John Maxwell

Certificate (if required).