

ANNUAL SURVEYS.

Rev. 20/10/66

No. 20203 Survey held at Liverpool Date 3rd to 13th October 1866
 on the iron ship "Kuslandshiel" Master Wummerson
 Tonnage 1057 Built at Birkenhead When built 1863
 By whom built J. Cover Owners Beatt & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock London having and flooring decks.

[Signature]

Last Survey, No. 3324 Port of Iron Classed A1
10.63

The present Condition of the Decks Waterways Comings Upper Deck Beams & Fastenings Lower Deck Beams & Fastenings Planksheers Sheerstrakes Topsides Wales Plank (Bottom) and Counter	Treenails <u>Rivets</u> Breasthooks and Stenson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Do Do at other places Keelsons Clamps and Shelves Ceiling Rudder Copper When put on	Windlass and Capstan <u>Good</u> Pumps Boats Masts, Yards, &c. Sails Anchors No. of } <u>Good</u> Cables } <u>and</u> Hawsers and Warps } <u>sufficient</u> Standing & Running Rigging
---	--	--

where seen Good

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen Good.
Bottom scraped clean and coated with Paint.
Is now in good and efficient Condition and in my opinion eligible
to remain as Classed A1.
 Committee's Minute Liverpool 19th October 1866
[Signature]

Character assigned A1 Certificate (if required)

No. 19 Survey held at Liverpool Date 6th to 12th Oct. 1866
 on the iron ship "Hano" Master Larinaga
 Tonnage 445 Built at Belfast When built 1863
 By whom built Harland Owners Hano & Co
 Port belonging to Bilbao Destined Voyage Havana
 If Surveyed Afloat or in Dry Dock Having having dock
3371

[Signature]


Last Survey, No. 2377 Port of Iron Classed A1
10.63

The present Condition of the Decks Waterways Comings Upper Deck Beams & Fastenings Lower Deck Beams & Fastenings Planksheers Sheerstrakes Topsides Wales Plank (Bottom) and Counter	Treenails <u>Rivets</u> Breasthooks and Stenson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Do Do at other places Keelsons Clamps and Shelves Ceiling Rudder Copper When put on	Windlass and Capstan <u>Good</u> Pumps Boats Masts, Yards, &c. Sails Anchors No. of } <u>Good</u> Cables } <u>and</u> Hawsers and Warps } <u>sufficient</u> Standing & Running Rigging
---	--	--

where seen Good

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen Good.
Bottom scraped clean and coated with the Swiss Composition.
Is now in good and efficient Condition and in my opinion
eligible to remain as Classed A1.
 Committee's Minute Liverpool 19th October 1866
[Signature]

Character assigned A1 Certificate (if required)



"Rutlandshire"
-20203-
-Clare-



© 2019

Lloyd's Register
Foundation