

REPORT of SURVEY for REPAIRS.

Triennial Survey

No. in Reg. Book, **No.** *733* Survey held at *London* Date *June 28th* 18 *66*
 on the *S. Star of Denmark* Master *J. H. Savage*
 Tonnage *998* Built at *Belfast* When built *1863* *6 mo*
 By whom built _____ Owners *Currie Corry & Co*
 Port belonging to *Belfast* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *T. J. W's dock & E. J. Dock*

Last Survey, No. *3258* Port *Iron.* Classed *12 A 5*
63

REPAIRS

The ceiling lifted as prescribed and the
 cement and bottom found in good condition.
 The outside painted with two coats of
 McInnes'

Present Condition of the

	<i>Good</i>	<i>Rivets</i>	<i>Good</i>	
Waterways	<i>do</i>	Breasthooks and Stemson	<i>do</i>	Windlass and Capstan
ings	<i>do</i>	Transoms, Pointers, and Crutches	<i>do</i>	Pumps
per Deck Beams & Fastenings	<i>do</i>	Timbers of the Frame at the openings	<i>do</i>	Boats
per Deck Beams & Fastenings	<i>do</i>	Ditto Ditto at other places	<i>do</i>	Masts, Yards, &c.
anksheers	<i>do</i>	Keelsons	<i>do</i>	Condition, how ascertained
erstrakes	<i>do</i>	Clamps and Shelves	<i>do</i>	Sails
osides	<i>do</i>	Ceiling	<i>do</i>	Anchors No. of
ules	<i>do</i>	Rudder	<i>do</i>	Cables
(Bottom) and Counter	<i>do</i>	Copper	<i>do</i>	Hawsers and Warps
		Whim	<i>do</i>	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. *Where seen good*

This vessel is now in good condition
 and is eligible in my opinion to remain

The Amount of Fee.....£ : : is received by me, *Classed 12 A 1*
 Special..... 1 : 1 : - *3/11/66* and be marked *(2 s 66)*
 Certificate (if required) : 5 : -

Committee's Minute *6th November* 18 *66*

Character assigned *12 A 1*

W. H. W. W. W.