

ANNUAL SURVEYS.

282

Rec 21/1/67

No. 8912 Survey held at Sunderland Date 28 Decem. 18 66
 on the Iron Blk "Onyx" Master Hutch
 Tonnage 420 Built at Sunderland When built 1864
 By whom built James Cairg Owners Weatherley
 Port belonging to Sunderland Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 3853 Port of Sunderland Classed A.1. 64.

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>3</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places <u>Good</u>	Sails <u>Well found</u>
Planksheers	Keelsons	Anchors No. of <u>2 Br. 12 & 16 lb</u>
Sheerstrakes	Clamps and Shelves	Cables <u>Complete</u>
Oppsides	Ceiling	Hawsers and Warps <u>Sufficient</u>
Vales	Rudder	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactory

At present the timber boards have been lifted and found the cement quite good. The bottom outside has been scraped and coated. She is in an efficient state and in my opinion entitled to remain as classed.

Senhouse Martindale.

Committee's Minute 22nd January 18 67
 Character assigned B 1 N.A.D.

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18 _____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Oppsides	Ceiling	Hawsers and Warps
Vales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18 _____
 Character assigned _____

