

# ANNUAL SURVEYS.

No. 2040 Survey held at Birkenhead Date Jan<sup>24</sup> 10<sup>th</sup> & 26<sup>th</sup> 1867  
 on the Ship Sam Adams Master J. Chambers  
 Tonnage 1422 Built at Greenock When built 1864  
 By whom built Scott Owners Lancaster Ship Owners Co (Limited)  
 Port belonging to Lancaster Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Men in Clover & Co's dry dock afloat

Last Survey, No. 4519

Port of Iron

Classed

A.1.  
65

The present Condition of the

Decks good  
 Waterways "  
 Comings "  
 Upper Deck Beams & Fastenings Iron  
 Lower Deck Beams & Fastenings good  
 Planksheers where  
 Sheerstrakes seen  
 Topsides  
 Wales  
 Plank (Bottom) and Counter Painted

Treenails  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches Iron  
 Timbers of the Frame at the Openings good  
 Keelsons where  
 Clamps and Shelves seen  
 Ceiling  
 Rudder  
 Copper When put on

Windlass and Capstan good  
 Pumps "  
 Boats good and complete  
 Masts, Yards, &c. "  
 Sails "  
 Anchors No. of 3 B. 15. 2 H.  
 Cables good where seen  
 Hawseers and Warps "  
 Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. - Bottom scraped and painted. - She is now in good condition and in my opinion eligible to remain as classed by A.1.  
 Committee's Minute Liverpool 1<sup>st</sup> February 1867  
 Character assigned A.1.

J. F. Light  
 Certificate (if required)

No. 246 Survey held at Birkenhead Date Jan<sup>24</sup> 17<sup>th</sup> & 25<sup>th</sup> 1867  
 on the Ship "Ellen" Master Valuer  
 Tonnage 508 Built at Glasgow When built 1865  
 By whom built Deerwick Owners St Andrew &  
 Port belonging to Liverpool Destined Voyage South America  
 If Surveyed Afloat or in Dry Dock Clayton's wood side graving dock.

Last Survey, No. 4434

Port of Iron

Classed

A.1.  
65

The present Condition of the

Decks good  
 Waterways "  
 Comings "  
 Upper Deck Beams & Fastenings Iron  
 Lower Deck Beams & Fastenings good  
 Planksheers where  
 Sheerstrakes seen  
 Topsides  
 Wales  
 Plank (Bottom) and Counter Painted

Treenails  
 Breasthooks and Stemson Iron  
 Transoms, Pointers, and Crutches good  
 Timbers of the Frame where  
 Keelsons Do Do at other places  
 Clamps and Shelves seen  
 Ceiling  
 Rudder  
 Copper When put on

Windlass and Capstan good  
 Pumps "  
 Boats good & sufficient  
 Masts, Yards, &c. "  
 Sails "  
 Anchors No. of 3 B. 15. 2 H.  
 Cables good where seen  
 Hawseers and Warps good  
 Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. - Bottom scraped and painted. - She is now in good condition, and in my opinion, eligible to remain classed A.1.  
 Committee's Minute Liverpool 1<sup>st</sup> February 1867  
 Character assigned A.1.

J. F. Light  
 Certificate (if required).



"Lam Carno"  
-20400-  
"River Eden"

2 1/2  
14/105/8.9  
96  
9  
1.15



© 2019

Lloyd's Register  
Foundation