

ANNUAL SURVEYS.

No. 3720 Survey held at Hull Date 6th Feb 1867
 on the Iron Steamer "Viceroy" Master R Leighton
 Tonnage 823 Built at Sunderland When built 1862
 By whom built Oswald Owners Geo & Co
 Port belonging to Hull Destined Voyage Hamburg
 If Surveyed Afloat or in Dry Dock On Humber Ship-way & afloat in Humber Est

Last Survey, No. 4690 Port of Hon Classified 9-A-1
 (1866) 4.66

The present Condition of the

Decks	<u>Good</u>	Treenails <u>new</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>Good</u>	Breasthooks and Stemson	<u>Good</u>	Pumps	<u>Good</u>
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	<u>Good</u>	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the Openings	<u>Good</u>	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Keelsons	<u>Good</u>	Sails	<u>Good</u>
Planksheers	<u>Good</u>	Clamps and Shelves	<u>Good</u>	Anchors No. of	<u>Good</u>
Sheerstrakes	<u>Good</u>	Ceiling	<u>Good</u>	Cables	<u>Good</u>
Topsides	<u>Good</u>	Rudder	<u>Good</u>	Hawsers and Warps	<u>Good</u>
Wales	<u>Good</u>	Copper	<u>Good</u>	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	<u>Good</u>	When put on	<u>Good</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Now done - The bottom cleaned and coated with Tar
is eligible in my opinion & remain as Classed A-1

Committee's Minute 8th February 1867

Character assigned 9-A-1

M Davidson

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classified _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	
	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18

Character assigned _____



© 2019

Certificate (if required).

Lloyd's Register Foundation