

ANNUAL SURVEYS.

5450
28235

No. 816 on the *BK Merle* Survey held at *London* Date *April 17th* 18 *67*
 Tonnage *281* Built at *London* Master *J. Hamlyn*
 By whom built *Westwood & Baillie* Owners *Scrutton*
 Port belonging to *London* Destined Voyage *N. Indies*
 If Surveyed Afloat or in Dry Dock *in Union & West India Dock*

Last Survey, No. *5077* Port of *Iron* Classed *A1*
9.66

The present Condition of the

Decks <i>where seen Good</i>	Treenails <i>Rivets where seen Good</i>	Windlass and Capstan <i>Good</i>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <i>3 B, 1 S, 2 K</i>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter <i>coaled with one coat of coal tar</i>	Copper <i>✓</i> When put on <i>✓</i>	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <i>where seen Good</i>	

Is now in good and efficient condition and in my opinion eligible to remain as classed

Committee's Minute *30th April* 18 *67*
 Character assigned *A1* *M.A.S.*

Thos Maxwell

Certificate (if required)

322 No. Survey held at *London* Date *April 20th* 18 *67*
 on the *S. Dundonald* Master *Kewley*
 Tonnage *591* Built at *Liverpool* When built *1861*
 By whom built *Vernon* Owners *Nicholson*
 Port belonging to *Liverpool* Destined Voyage
 If Surveyed Afloat or in Dry Dock *in Union Dock*

Last Survey, No. *S.S. No. 1-66* *4603* Port of *Iron* Classed *A1*
3.66 *S.S. No. 1-66*

The present Condition of the

Decks <i>where seen Good</i>	Treenails <i>Rivets where seen Good</i>	Windlass and Capstan <i>Good</i>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <i>3 B, 1 S, 1 K</i>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter <i>now painted with 2 coats of all lines paint</i>	Copper <i>✓</i> When put on <i>✓</i>	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <i>where seen Good</i>	

Is now in good and efficient condition and in my opinion eligible to remain as classed

Committee's Minute *30th April* 18 *67*
 Character assigned *A1* *M.A.S.*

Thos Maxwell

Certificate (if required).