

5624  
Iron

2877

# REPORT of SURVEY for REPAIRS.

No. in Book. **No.** Survey held at London Date July 26<sup>th</sup> 1867  
on the Sew "Camilla" Master Mitchell  
Tonnage 540 Built at Newcastle When built 1866  
By whom built \_\_\_\_\_ Owners Lond. Str. Ship Co  
Port belonging to London Destined Voyage Mediterranean  
If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 4841 Port Iron. Classed A 1  
7.66

## REPAIRS

A few rivets renewed and the bottom painted with two coats of line and one of Tallow -

### Present Condition of the

	Treenails	Rivets	
Decks			Windlass and Capstan
Waterways			Pumps
Comings			Boats
Upper Deck Beams & Fastenings			Masts, Yards, &c.
Lower Deck Beams & Fastenings			Condition, how ascertained
Planksheers			Sails
Sheerstrakes			Anchors No. of
Topsides			Cables
Wales			Hawsers and Warps
Plank (Bottom) and Counter			Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is eligible in my opinion to remain at classed A 1

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 2<sup>nd</sup> August 1867

Character assigned A 1

Thos. W. Wawn



© 2019

Lloyd's Register Foundation

IRON441-0086