

4556

Iron Ship 5635 ANNUAL SURVEYS.

25759

No. 308 Survey held at London Date July 20th 1867
 on the Iron Screw "Druid" Master Ferguson
 Tonnage 696 Built at Middlesborough When built 1865
 By whom built _____ Owners Hudson &
 Port belonging to Sunderland Destined Voyage not fixed
 If Surveyed Afloat or in Dry Dock Catcliff Dry Dock

Last Survey, No. 4554 Port of None Classed B. 1.
66

The present Condition of the

Decks	} <u>good</u>	Treenails <u>Rivets</u>	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Boats <u>three</u>	
Comings	} <u>where</u>	Transoms, Pointers, and Crutches	} <u>where</u>	Masts, Yards, &c.	} <u>where</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Sails	
Lower Deck Beams & Fastenings	} <u>seen</u>	Do Do at other places	} <u>seen</u>	Anchors No. of <u>3 B. 15 2 K</u>	} <u>seen</u>
Planksheers		Keelsons		Cables	
Sheerstrakes	} <u>seen</u>	Clamps and Shelves	} <u>seen</u>	Hawsers and Warps	} <u>seen</u>
Topsides		Ceiling		Standing & Running Rigging	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>		} <u>seen</u>
Plank (Bottom) and Counter		Copper <u>Paint</u> When put on <u>now</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
Now done, the bottom scraped and painted with oxide of Iron & Zinc - She is now in good condition fit in my opinion to remain as classed B. 1.
 Committee's Minute 30th July 1867
 Character assigned B. 1. M.S.

Certificate (if required)

J. J. Smith

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____


Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____
 Character assigned _____



IRON44-0093