

ANNUAL SURVEYS.

No. 350 Survey held at London Date August 3rd 18 67
 on the S "Durham" Master L. Vaux
 Tonnage 998 Built at Sunderland When built 1866
 By whom built Oswald Owners Temperley
 Port belonging to London Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock in Thames Iron works and East India Dock

Last Survey, No. 4806 Port of Iron Classed A1
7.66

The present Condition of the

Decks <u>where seen Good</u>	Ironails <u>Rivets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 B. 1 S. 2 K.</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Scraped bottom and painted with two coats of oxide of iron and one of anti-fouling paint.
 Is now in good and efficient condition and in my opinion eligible to remain as classed

Committee's Minute 9th August 18 67
 Character assigned A1 M.S.

John Maxwell

Certificate (if required).

No. 884 Survey held at London Date August 2nd 18 67
 on the S "Superb" Master E. Jones
 Tonnage 1457 Built at London When built 1866
 By whom built Green Owners R. & H. Green
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock in Green's lower & East India Dock

Last Survey, No. 5117 Port of Iron Classed A1
10.66

The present Condition of the

Decks <u>where seen Good</u>	Ironails <u>Rivets where seen Good</u>	Windlass and Capstan <u>where seen Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 B. 1 S. 2 K.</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Scraped and painted bottom.

Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 9th August 18 67
 Character assigned A1 M.S.

John Maxwell

Certificate (if required).

IRON44-0094