

5640  
*Iron Ship*  
**ANNUAL SURVEYS.**

*28474*

12 No.                      Survey held at London Date Aug 1<sup>st</sup> 3<sup>rd</sup> 1867  
 on the Iron Screw "Galicia" Master J. W. Stranghan  
 Tonnage 750 Built at Hartlepool. When built 1866.  
 By whom built Richardson Owners J. Hall jun &  
 Port belonging to London Destined Voyage Gibraltar  
 If Surveyed Afloat or in Dry Dock Under Dry Dock

Last Survey, No. 5204 Port of Iron. Classed B.1.  
11.66

The present Condition of the

Decks Waterways Comings Upper Deck Beams & Fastenings Lower Deck Beams & Fastenings Planksheers Sheerstrakes Topsides Wales Plank (Bottom) and Counter	Treenails <u>Rivets</u> Breasthooks and Stemson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Do Do at other places <u>where</u> Keelsons Clamps and Shelves Ceiling Rudder Copper <u>Paint</u> When put on <u>now</u>	Windlass and Capstan Pumps Boats Masts, Yards, &c. Sails Anchors No. of <u>B.P. 1526</u> Cables Hawser and Warps Standing & Running Rigging
---	---	---

} good } good } good  
 } where } seen } seen

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen  
*Now done, the Bottom scraped and painted with Red lead - the shaft bearing refitted, and rubbing pieces fitted to the side of bar iron 2 1/2 x 1 1/4. She is now in good condition, fit in my opinion to remain as classed*

Committee's Minute 13 August 1867 B.1. *H. J. M. S. H.*  
 Character assigned B.1. M.S. Certificate (if required)

No.                      Survey held at                      Date                      18              
 on the                      Master                       
 Tonnage                      Built at                      When built                       
 By whom built                      Owners                       
 Port belonging to                      Destined Voyage                       
 If Surveyed Afloat or in Dry Dock                     

Last Survey, No.                      Port of                      Classed                     

The present Condition of the

Decks Waterways Comings Upper Deck Beams & Fastenings Lower Deck Beams & Fastenings Planksheers Sheerstrakes Topsides Wales Plank (Bottom) and Counter	Treenails Breasthooks and Stemson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Do Do at other places Keelsons Clamps and Shelves Ceiling Rudder Copper When put on	Windlass and Capstan Pumps Boats Masts, Yards, &c. Sails Anchors No. of Cables Hawser and Warps Standing & Running Rigging
---	--	--

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways

Committee's Minute                      18              
 Character assigned