

ANNUAL SURVEYS.

No. 413 Survey held at London Date July 25th to 27th 1867
 on the Iron Screw "Graham Hall" Master J. White
 Tonnage 583 Built at Stockton When built 1857
 By whom built _____ Owners Pearse & Co.
 Port belonging to W. Hartlepool Destined Voyage Lisbon
 If Surveyed Afloat or in Dry Dock Limetide (Dry Dock)

Last Survey, No. 4812 Port of Iron Classed B 1.16
 (SS. No 3. 66)

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings	} <u>where</u>	Transoms, Pointers, and Crutches	} <u>where</u>	Boats <u>four</u>	} <u>where</u>
Upper Deck Beams & Fastenings		Timbers of the Frame <u>at the Openings</u>		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>seen</u>	Do Do at other places	} <u>seen</u>	Sails	} <u>seen</u>
Planksheers		Keelsons		Anchors No. of <u>3 BISH</u>	
Sheerstrakes	} <u>seen</u>	Clamps and Shelves	} <u>seen</u>	Cables	} <u>seen</u>
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper <u>Paint</u> When put on <u>now</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
now done. The shaft bearing refitted and fastened and a new pin fitted
to the Propeller. the Bottom cleaned and painted with Coal Tar.
She is now in good condition fit in my opinion to
remain as classed B. S.
 Committee's Minute 2nd August 1867
 Character assigned B 1 J. J. Cornish

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	} _____	Treenails	} _____	Windlass and Capstan	} _____
Waterways		Breasthooks and Stemson		Pumps	
Comings	} _____	Transoms, Pointers, and Crutches	} _____	Boats	} _____
Upper Deck Beams & Fastenings		Timbers of the Frame <u>at the Openings</u>		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} _____	Do Do at other places	} _____	Sails	} _____
Planksheers		Keelsons		Anchors No. of _____	
Sheerstrakes	} _____	Clamps and Shelves	} _____	Cables	} _____
Topsides		Ceiling		Hawsers and Warps	
Wales	} _____	Rudder	} _____	Standing & Running Rigging	} _____
Plank (Bottom) and Counter		Copper _____ When put on _____			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register Foundation
 Certificate (if required).

1R0W441-0100